


Example of outlet in the tankwall



Reinforcement of hole in the tankwall



Pipe-connection to sidewall

Installation

The best way to install is when the tank and the liner are installed. Because then you do not have to manipulate the liner anymore. Drill a hole from the inside to the outside of the tank at the place of the outlet. Then drill the holes from the outside and use the plate as a sample. The hole in the middle should be at least 65 mm so you can put your hand through to install the bolts from the outside.